C42)

9 October 1957

TO:

WRSP(3)

FROM:

R-W

INFO:

WRSP(2)

WRSP(1)

HEADQUARTERS /

SUBJECT: 25X1A

Electronics Systems Report for July 1957

From Regarding your request for information on the bias values for the information recorders, this is to advise that the deviation of 5 - 10% in bias current should cause no concern.

At the present time there are no MP books available for your use. Steps have been taken to make this information available to you as soon as possible.

In reporting component failures, if the cause of failure is known, please indicate the reason.

In relaying so-called "Publication" errors, we are finding that some of these are design errors, not errors in publication. At the time of reporting, please indicate which type of error you have found. This will expedite correction.

25X1A

hcp



